




1





2x  m8	2x  8x70 mm p7	4x  s8
 13		



2
▼





12x  7x50 mm e1	1x  4 I4
--	---





3
▼



18x  7x40 mm	e2	1x  4	I4
---	-----------	--	-----------



4
▼






5
▼





6
▼




180°



3x	
8x45 mm	p5
3x	
	s8
	
	13






7




8
▼

2x  s8	1x  4 I4	2x  M6x70 mm c7	2x  6x12 mm m1
--	---	--	---



9



 13	3x  s8	3x  8x45 mm p5
---	---	--

