



PZ2




PZ3




1/10

ANADIA II 90x200 FSC



A1


x 4



Euro 6,3x13

A2


x 20



WPM 6x35

A3


x 12



US 5x40

A4


x 2



US 5x40

A5


x 4





US 5x40

A6


x 4



2



1



2




3




4



5



1



A1+A2


A1

A2

2


2/10

A1+A2








3

A4+A5



4








PZ2



PZ3



4/10

ERGO DNO 90x200 FSC

US 4x16



A7 x 12



A8 x 2



A9 x 2

WP M6x25



A10 x 8

UP 5x20




A11 x 18

f-30 h-4



A12 x 18




A18 x 4



A19 x 4





3



4




5




A16

3

A15 x 18




3




A13

3




3

A14



3

A14



A17


A17

3


3

6

5/10







7






45




11


7/10



12




13




14


8/10



15




16




17

9/10




18



19


A11+A14+A15

A11+A13+A15




20

10/10



21



22

