





# Xenia




1




2





3




4








5



|   |     |     |
|---|-----|-----|
| 1 | 1 x | 1/2 |
| 2 | 4 x | 2/2 |
| 3 | 2 x | 2/2 |
| 4 | 2 x | 2/2 |
| 5 | 1 x | 2/2 |




2/2




I.

1



|   |       |
|---|-------|
| A | M8x10 |
|   | 12x   |
| E | 6MM   |
|   | 1x    |
|   | 75%   |


2




|   |       |
|---|-------|
| A | M8x10 |
|   | 6x    |
| E | 6MM   |
|   | 1x    |
| B | M6x12 |
|   | 2x    |
| D | 4MM   |
|   | 1x    |
|   | 75%   |

II.

3




4



|   |       |
|---|-------|
| A | M8x10 |
|   | 6x    |
| E | 6MM   |
|   | 1x    |
| B | M6x12 |
|   | 2x    |
| D | 4MM   |
|   | 1x    |
|   |       |




III.

5



|                                                                                     |                                                                                     |     |
|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|-----|
| C                                                                                   |  | Ø30 |
|                                                                                     |                                                                                     | 4x  |
|  |                                                                                     |     |

6



LE TRI  
+ FACILE



+



Séparez les éléments avant de trier