




Mx- 152





















COLLI 1/4				
A	900	x	599	1x
B	866	x	561	1x
F	425	x	540	2x
H	425	x	540	1x
N	866	x	70	1x
V+U	690	x	150	2x
D1	448	x	404	2x
C1+B1	450	x	100	4x

COLLI 3/4				
C+D	2142	x	580	2x
P	2073	x	438	2x

COLLI 2/4				
E	2056	x	561	1x
M	425	x	561	1x
H	425	x	540	3x
A1	394	x	100	2x

COLLI 4/4				
R	2066	x	444	1x
S	1712	x	444	1x
T	174	x	444	2x

0013K	1x	0001K	16x	0019K	28x	0018K	24x	0094K	4x
									
		8x40							
0002K	5x	0054K	16x	0003V	23x	0060K	5x	0009K	16x
									
				3x16					
0004K	16x	0003K	2x	0149K	4x	0009V	8x	0002V	27x
									
						4x50		3,5x16	
0018U	2x	0004V	4x	0015K	7x	0014K	7x		
									
		4x30							
0109K	1x	0051K	1x	0018V	1x	0011V	8x		
									
				5x50		4,5x35			
		0006K	4x	0024K	4x				
									
		M4x10							

01

02

03

04

05

06

0

1

2

3

4


5

6

1.)

0001K

16x



8x40

C


D

E

B

N


0001K



2.)

0014K


7x



D

C

0014K



3.)

0003K 2x

0024K 4x

0002V 12x

3,5x16

I.

0024K

0002V

II.

0024K

0002V

III.

0002V

0024K

0003K

D

E

4.)

0019K 6x

E

E

0019K

5.)

0019K 22x

D

C

A

B

T

T

0019K

X

✓

6.)

0003V 10x

0002K 5x

3x16

D

C

N

1/2



0002K

0003V

0003V




20mm

7.)






0054K	2x	0018K	2x

8.)




0054K	4x	0018K	6x

9.)




0054K	4x	0018K	10x


10.)



11.)



12.)



13.)

A

B

C

D

E

H

H

H

H

0009K

16x

14.)

0002V

14x

0015K

7x

3,5x16

15.)

0018V

1x

0051K

1x

0002V

1x

0109K

1x

5x50

3,5x16

16.)

2x

I.

A1

B1

C1

II.

A1

B1

C1

D1

III.

A1

B1

C1

T

IV.

T

D1

C1

A=B

B

A

0004K	4x	0011V	8x	0094K	4x
		4,5x35			

0011V

0011V

0094K

0004K

17.)

0004V	4x	0018U	2x	0006K	4x
4x30				M4x10	

A

D

E

C


0004V

0004V

0018U

0006K

18.)



0149K	4x	0009V	8x
