



05690006-03







PART LIST



X3



2 PEOPLE



## HARDWARE LIST

A X62



DIA15x11mm

B X62



DIA6x40mm

C X34



DIA8x35mm

D X86



DIA3x14mm

E X16



DIA3x12mm

F X5



M4x25mm

G X4



H X4



I X16



J X8



K X5



L X62



DIA15mm

M X2



N X2



DIA3x50mm

O X2



P X2



Q X1



R X12



DIA3x30mm

S X6



M6x40mm

T X1



U X4







DIA6x15mm





V X6




STEP 1



STEP 2




STEP 3






|                                                                                     |            |
|-------------------------------------------------------------------------------------|------------|
| <b>B</b>                                                                            | <b>X12</b> |
|  |            |
| <b>DIA6x40mm</b>                                                                    |            |

STEP 4



|                                                                                     |            |                                                                                     |           |                                                                                     |           |
|-------------------------------------------------------------------------------------|------------|-------------------------------------------------------------------------------------|-----------|-------------------------------------------------------------------------------------|-----------|
| <b>B</b>                                                                            | <b>X20</b> | <b>D</b>                                                                            | <b>X4</b> | <b>P</b>                                                                            | <b>X2</b> |
|  |            |  |           |  |           |
| <b>DIA6x40mm</b>                                                                    |            | <b>DIA3x14mm</b>                                                                    |           |                                                                                     |           |

STEP 5





|           |    |
|-----------|----|
| C         | X4 |
|           |    |
| DIA8x35mm |    |

|            |    |
|------------|----|
| A          | X6 |
|            |    |
| DIA15x11mm |    |

|         |    |
|---------|----|
| L       | X6 |
|         |    |
| DIA15mm |    |

STEP 6




|            |    |
|------------|----|
| A          | X6 |
|            |    |
| DIA15x11mm |    |



|         |    |
|---------|----|
| L       | X6 |
|         |    |
| DIA15mm |    |

|           |    |
|-----------|----|
| C         | X4 |
|           |    |
| DIA8x35mm |    |

STEP 7



STEP 8




|                                                                                       |    |
|---------------------------------------------------------------------------------------|----|
| C                                                                                     | X4 |
|  |    |
| DIA8x35mm                                                                             |    |






|                                                                                       |     |
|---------------------------------------------------------------------------------------|-----|
| A                                                                                     | X10 |
|  |     |
| DIA15x11mm                                                                            |     |

|                                                                                       |     |
|---------------------------------------------------------------------------------------|-----|
| L                                                                                     | X10 |
|  |     |
| DIA15mm                                                                               |     |

STEP 9







STEP 10













## STEP 11




## STEP 12





STEP 13





STEP 14





## STEP 15



## STEP 16




STEP 17




|            |     |         |     |
|------------|-----|---------|-----|
| A          | X12 | L       | X12 |
|            |     |         |     |
| DIA15x11mm |     | DIA15mm |     |

STEP 18



## STEP 19



K X3



F X3




M4x25mm

R X12









DIA3x30mm








## STEP 20





STEP 21



STEP 22



## STEP 23



## STEP 24

