




























				PCS	
①	188.5	43	80	×1	1/2
②	188.5	20	67	×1	1/2
③	105	11	65	×1	2/2
④	105	11	65	×1	2/2
⑤	50	94	12	×2	1/2
⑥	40	40	10	×2	1/2
⑦	21.5	26	20.7	×1	1/2

Fittings / Beschläge




PC H 30

× 4




PC1 120

× 2



H1 4x40

× 2



S M6 x 80

× 2




Sa Ø18 / Ø7


× 2




P

× 2







A




B




1




2




3




4




5




6



1




2




3




4




1




2



3






4



H1 4x40

× 2





Stoffprobe im Reparaturfall
Fabric sample in case of repair

