



# ASSEMBLY INSTRUCTION

## 16940014-01





A x 8




M6x20 mm

B x 8




M6x25 mm

C x 6




M6x40 mm

D x 22




M6x45 mm

E x 16



M6x55 mm

F x 4



M6x80 mm

G x 4




M8x20 mm

H x 2



M8x35 mm

J x 2



M8x45 mm

K x 48




Ø6x14x1 mm

L x 16



Ø8x16x1 mm

M x 4




Ø8x16x3 mm

N x 8




M8 mm

P x 16




45x45x65 mm

Q x 3






4 mm


R x 1




90x25x2 mm




**Components:**



① x2




② x2



③ x2



④ x2




⑤ x2




⑥ x2




⑦ x2




⑧ x2




⑨




⑩



⑪




⑫




⑬



⑭



⑮ x2




⑯ x2



⑰




⑱




1

x2





2

x2





3

x2




4

x2




x2





5

x2







6

x2





7

x2





8


x2




9




10





11





12





13





14





15





16




17




18




19





20




21



22



23



24

