







A





B





A  Ax3 M6x40	B  Bx3 M8	C  Cx1 4	D  Dx6
E  Ex1	F  Fx24 M6x20	G  Gx1 Plastic	




1a






1b






2a




2b







3a

D		Dx4	F		Fx16 M6x20	E		Ex1	G		Gx1 Plastic
---	---	-----	---	---	---------------	---	--	-----	---	---	----------------






3b




D		Dx4	F		Fx16 M6x20	E		Ex1	G		Gx1 Plastic
---	---	-----	---	---	---------------	---	--	-----	---	---	----------------





4a



4b





Attention!

