



25130010/04



Max
35KG








2PER



30 MIN


PART LIST





HARDWARE LIST

A X24



B X24



C X24



D X24



DIA8x40mm

E X24



DIA3x15mm

F X2



DIA3.5x18mm

G X34



DIA3.5x15mm


H X16




I X2




J X2



K X2




L X5



M X8




N X1



O X2




P X2




DIA3x50mm


Q X2




STEP 1




STEP 2




STEP 3





STEP 4




STEP 5








STEP 6










STEP 7




STEP 8




STEP 9









STEP 10




STEP 11




STEP 12







STEP 13



STEP 14



STEP 15



P	X2
 DIA3x50mm	
Q	X2
