



ASSEMBLY INSTRUCTION - 23040041-01




ASSEMBLY INSTRUCTION - 23040041-01


(A) 8pcs




(B) 2pcs




(B1) 1pc




(B2) 1pc




(C) 1pc




(C1) 1pc




(C2) 1pc




(C3) 1pc




(D) 1pc




(D1) 1pc














(E) 1pc




(E1) 1pc




ASSEMBLY INSTRUCTION - 23040041-01

<p>Ⓔ 1pc</p> 	<p>Ⓕ 2pcs</p> 			
<p>Ⓖ 1pc</p> 	<p>Ⓖ1 1pc</p> 			
<p>Ⓖ2 3pcs</p> 	<p>Ⓖ3 1pc</p> 			
<p>Ⓕ 4pcs</p> 	<p>Ⓕ1 4pcs</p> 			
<p>Ⓕ2 1pc</p> 				
<p>① 13pcs</p>  <p>M6x40</p>	<p>② 10pcs</p>  <p>M6x25</p>	<p>③ 50pcs</p>  <p>M6x15</p>	<p>④ 73pcs</p>  <p>M6</p>	<p>⑥ 2pcs</p> 
			<p>⑤ 16pcs</p>  <p>M4x15</p>	<p>⑦ 1pc</p> 

ASSEMBLY INSTRUCTION - 23040041-01





1



③x16  M6x15	④x16  M6
--	---

ASSEMBLY INSTRUCTION - 23040041-01

2



①x6



④x6



M6x40

M6

3




⑤x4



ASSEMBLY INSTRUCTION - 23040041-01


4



②x2
M6x25

④x2
M6


5




②x3
M6x25

④x3
M6

ASSEMBLY INSTRUCTION - 23040041-01




1



③x16  M6x15	④x16  M6
--	---


ASSEMBLY INSTRUCTION - 23040041-01

2



①x6 M6x40	④x6 M6
--------------	-----------




3






⑤x4

ASSEMBLY INSTRUCTION - 23040041-01

4




5




ASSEMBLY INSTRUCTION - 23040041-01

6




①x1	②x2	④x3
		
M6x40	M6x25	M6




7



ASSEMBLY INSTRUCTION - 23040041-01



1



2

