






BRUCE





20min





PZ2



I




II



Ax2

Bx5




H=135 mm

Cx1




H=135 mm

Dx2



H=130-200 mm

Ex20




5x30



PZ2

1

Bx2



H=135 mm




Ex8



5x30



PZ2



2

Bx3



H=135 mm

Cx1



H=135 mm

Dx2








H=130-200 mm


Ex12



5x30



3



4

