




H 100



00020010-26



 A 8 L=544mm	 B 8	 E1 8	 HG 4	 J 4	 K 2	 K16 2
 L1 1	 O 1	 P5 8	 P7 20	 P8 4	 S 2	 U8 4
 8x30mm 8	 6,4 x 50mm 8	 3.5x13mm 8	 35/0mm 4	 5/19mm 4	 3.0x20mm 20	 4.0x30mm 4




ISM-KUH-01232








KUH.30005

KUH.40011

KUH.10020 x2	580x290x16
KUH.30005	966x250x16
KUH.40011 x2	967x276x16
KUH.60016	576x491x2,5
KUH.60017	576x491x2,5
KUH.70367 x2	576x496x16




$\pm 8 \times 30 \text{ mm}$  A	$\pm 4.0 \times 30 \text{ mm}$  P8	 K
8	4	2




2

6,4 x 50mm




B

4





O

1




E1


4



KUH.40011




B




KUH.10020



B




KUH.40011





O


B



E1



3




KUH.40011

KUH.10020

KUH.40011


KUH.10020

6,4 x 50mm




B

4



O





1







E1




4

4





5











Ø10mm



x4





7

±5/19mm



J

4



8

±35/0mm



HG



4

±3.5x13mm






P5








8





9




10





4.0x27mm



x2

4.0x27mm

