








ASSEMBLY INSTRUCTIONS: 12540075/01


BELDANO

MX Logistika SL, spol. s.r.o
Roznavska 32
SK-82104 Bratislava 2-Ruzinov, Slovakia




ASSEMBLY INSTRUCTIONS: 12540075/01


No	Name of Hardware	Q.ty	Fig
1	Screw M6x60	4	
2	Screw M6x40	2	
3	Screw M4x12	22	
4	Bas L 20x20	6	
5	Bas L 30x20	5	
6	Allen Key	1	




A x 1




B x 1




C x 1




D x 1



E x 2




F x 1




G x 1

ASSEMBLY INSTRUCTIONS: 12540075/01

Step 1:




Step 2:



ASSEMBLY INSTRUCTIONS: 12540075/01

Step 3:



Step 4:

