


ASSEMBLY INSTRUCTION: 12540078/01



BELDANO

MX Logistika SL, spol.s.r.o
Roznavska 32
SK-82104 Bratislara, Slovakia




ASSEMBLY INSTRUCTION: 12540078/01



No	Name of Hardware	Fig	Qty
A	Washer		8
B	Bolt M6x60		8
C	Leveler Foot		4
D	Allen Key		1




Step 1:



ASSEMBLY INSTRUCTION: 12540078/01


No	Name of hardware	Fig	Qty
A	Screw M6x70		6
B	Screw M6x35		7
C	Screw M6x50		3
D	Leveler Foot		4
E	Allen Key		2

7









x1


8




x1




Step 1:




Step 2:




Step 3:






Step 4:













Step 5:




ASSEMBLY INSTRUCTION: 12540078/01


No	Name of hardware	Fig	Qty
A	Screw M6x70		6
B	Screw M6x35		12
C	Screw M6x50		8
D	Leveler Foot		4
E	Allen Key		2




Step 1:




Step 2:




Step 3:






Step 4:





Step 5:













Step 6:




ASSEMBLY INSTRUCTION: 12540078/01


No	Name of hardware	Fig	Qty
A	Screw M6x70		6
B	Screw M6x35		12
C	Screw M6x50		8
D	Leveler Foot		4
E	Allen Key		2




Step 1:




Step 2:




Step 3:






Step 4:



Step 5:



Step 6:



Finish.