






Ax1		Bx6	Cx1		Dx1	Ex6	Fx2	Gx2	Hx2	
Ix4	Kx2	Lx1		Mx1	Nx1	Ox1	Px1			
Qx1	Rx1	Sx1	Tx1	Ux2	Vx1	No	Part Image	Part Name	Q.ty	
						1		Bolt M6 x15	62	
						2		Bolt M6 x40	8	
						3		Bolt M6 x50	20	
						4		Eru M6	20	
						5		Washer M6	90	
						6		Cole 10	1	
						7		M4 Allen key	1	


Step 1




Finsh




Step 1




Step 2



Step 3



Step 4



Finish

