































A	B1	B2	C1	C2	C3	D
1	F78-9001	-5	1899	446	2,5	3/5
2	F80-0002	-9	445	189	15	5/5
3	F80-0003	-6	445	379	15	5/5
4	F80-0004	-6	1316	445	15	5/5
5	F80-1018	-6	1968	523	15	4/5
6	F80-1019	-5	1873	503	18	3/5
7	F80-1020	-6	1968	523	15	4/5
8	F80-3002	-4	431	480	18	1/5
9	F80-3004	-3	431	503	18	1/5
10	F80-3021	-	880	503	15	2/5
11	F80-4003	-7	460	40	22	1/5
12	F80-4011	-	880	65	15	2/5
13	F80-4012	-	911	120	22	2/5
14	F80-5401	-2	382	110	15	2/5
15	F80-5402	-3	382	180	15	2/5
16	WSP-9534	B.53	406	408	2,5	1/5
17	WSR2-5007	-	400	110	12	2/5
18	WSR2-5008	-	400	110	12	2/5
19	WSR4-5007	-	400	180	12	2/5
20	WSR4-5008	-	400	180	12	2/5
21	dr-422		422	22	15	1/5





**2**


3



4



2x




5




1x

10



6




3x




1x


10




4x




3x




7




8




9




10





11




12




13


A=B



12x



8x




4x




16x


14



15




16





17

2x





2x



I





4x




II




4x





2x




III




IV



A=B




w5\DL







4x

18



19



20**2x**

21

