




ASSEMBLY INSTRUCTION: 12540016/01




MX Logistika SL, spol.s.r.o
ROZNAVSKA 32
SK-82104 BRATISLAVA, Slovakia




ASSEMBLY INSTRUCTION: 12540016 01

No	Name of Hardware	Fig	Qty	A	B	C
1	Screw M6x60		8			
2	Allen Key		1	x1	x2	x2

Step 1:




Step 2:




ASSEMBLY INSTRUCTION: 12540016 01


Step 3:



Step 4:




Step 5:




ASSEMBLY INSTRUCTION: 12540016/01

Step 1:



Step 2:



Step 3:

