




PZ2




PZ3



1/11


ALLOS 180x200 FSC




x 4




x 20



x 12




x 2




x 4



x 4



2



1



2




3




4



5





1



A1+A2

A1




A2

2


2/11

A1+A2








3

A4+A5



4








PZ2



PZ3



4/11

ERGO DNO 120-140-160-180x200 FSC

US 4x16



A7 x 12



A8 x 2



A9 x 2

WP M6x25



A10 x 8

UP 5x20




A11 x 18

f-30 h-4



A12 x 18



A18 x 4



A19 x 4





3



4



5



A16

3

A15 x 18

3

A13

3

A14

3

A14

3

A17

3

A17

3

6



5/11

A16

A9+A7

A9 →

← A7




7

A8+A7

A7 →

← A8












45





1 - x2	13 - x4	8 - x2	15 - x1	16 - x1	5 - x36	6 - x18
2 - x1	7L - x1		7P - x1	9 - x1	11 - x8	12 - x4
3 - x2	10 - x6					
14 - x1	4 - x36					











18

10/11




19



20


A11+A14+A15

A11+A13+A15




21

11/11



22



23

