


A	1x	294.5x287
B	1x	294.5x287
C	1x	1951x309
D	1x	1951x309
G	1x	1949x310
H	3x	294.5x277
H1	2x	294.5x287
I	1x	690x320.5
J	1x	690x320.5
F	1x	294.5x96


Z1	20x	
Z2	1x	
Z16	10x	
Z29	12x	
Z30	16x	
Z33	16x	
Z178	12x	
Z58	4x	
Z78	12x	
Z81	1x	
Z90	4x	
Z96	1x	
Z156	18x	
Z140	1x	
Z166	2x	

Z191	4x	
------	----	--

Z106	2x	
------	----	---





KL 09 - L




KL 09 - R







2.



2.




5.



Z16	4x	 3/8x16
Z191	2x	
Z58	2x	 M4x25
Z106	1x	
Z166	1x	

1x690x320.5

4.



Z16	4x	
Z191	2x	
Z58	2x	
Z106	1x	
Z166	1x	

1x690x320.5

5.

Z1	4x
----	----

F	1x	294.5x96
---	----	----------

7.

A,B,H1	4x	294.5x287	F	1x	294.5x96
C,D	2x	1951x309	G	1x	1849x310

Z29	12x
-----	-----

KL 09 - L

6.

Z1	16x
Z30	16x

A	1x	294.5x287
B	1x	294.5x287
H1	2x	294.5x287

7.

A,B,H1	4x	294.5x287	F	1x	294.5x96
C,D	2x	1951x309	G	1x	1849x310

Z29	12x
-----	-----

KL 09 - R

