




EVE/WICKIE








195 cm




















72h






60 min

				
A x 4	B x 1	C x 1	D x 2	E x 12
				
F x 8	G x 2	H x 4	I x 26	J x 2
				
K x 4	L x 6	M x 2	N x 6	O x 1
				
P x 1				




1/5




Article number	PSC	Package
1	x1	1/5
2	x1	1/5
3	x1	1/5
4	x1	2/5
5	x1	3/5
6	x1	4/5
7	x1	2/5
8	x1	5/5



1





2







3




4






5



6







Ex6

3,5x30


7




8



9




10





 M8x60
Jx2

11



 Ix2	M8x20	 Dx2	 Px1
---	-------	--	---


12



5x30
Gx2

13


Ⓔ screw all screws 100%




4x45
Fx4

Kx2


14




15



16





M8x16

Hx4




Mx2




Ox1

14/15

17



18



① screw all bolts 100%

19

