




HU 60 Blocktype Varianto

Montageanleitung / Notice de montage / Assembly instruction


Flex-Well Vertriebs GmbH
Industriestr. 80
32120 Hiddenhausen
info@flex-well.de



DSPU 100 Blocktype Varianto

Montageanleitung / Notice de montage / Assembly instruction

Flex-Well Vertriebs GmbH
Industriestr. 80
32120 Hiddenhausen
info@flex-well.de





4x

4x

14x

4x

4x





4x

3,5x15
8x


10x


2x

2x



3,5x30
4x






2x 2x 4x




Ø 5mm 8x 8x 12x





H 30 / H 40 / H 50 / H 60 / KH 60-32 / HG 50 / HGH 50 / H 50-89 / H 60-89 -Varianto

Montageanleitung / Notice de montage / Assembly instruction


Flex-Well Vertriebs GmbH
Industriestr. 80
32120 Hiddenhausen
info@flex-well.de



4x 12x 2x 1x 4x



8x 2x 2x



H 80 / H 100 / HG 100 / HGH 100

Varianto

Montageanleitung / Notice de montage / Assembly instruction

Flex-Well Vertriebs GmbH
Industriestr. 80
32120 Hiddenhausen
info@flex-well.de

