




INSTRUCTION SHEET

25820005/04





ax12



bx12



cx16



dx1



ex6



fx1



gx1



hx2



ix14



jx4




kx6



lx4



mx4



nx1












ox1







px1


1






2




3



4



5




6



7


ATTENTION

**PLEASE STICK THIS PAPER TO THE WALL BEFORE
DRILLING. USE " + " SIGN AS YOUR GUIDE**







kx4

8





ix2

9






10




kx2

11



12



ix4

13

