



90 min


US 40

00020010-06



 A	 B	 B2	 C5	 D2	 E1					
12	8	2	2	2	8					
 E9	 F2	 HG	 L11	 J	 L	 M2	 O	 P4	 P5	
2	4	2	1	4	2	8	1	2	8	
 P7	 R3	 S	 U	 T15	 T14	 U8				
8	4	2	2	2	2	2				

ISM-KUH-01236




KUH.60177



KUH.30009





KUH.40025

KUH.10343	815x550x16
KUH.10344	815x550x16
KUH.20070	400x600x38
KUH.30009	366x430x16
KUH.40025	367x485x16
KUH.60027	713x385x2,5
KUH.60177	337x446x2,5
KUH.70820	133x396x19
KUH.70825	576x396x19
KUH.90003	367x100x16
KUH.90004	367x100x16
KUH.90039	399x95x16
WST.0115	450x80x12
WST.0116	450x80x12
WST.0062	327x80x12









1

$\pm 12/10\text{mm}$  C5 2	$\pm 8 \times 30\text{mm}$  A 4
--	---









2

$\pm 6 \times 42\text{mm}$  B2 2












3





$L=20\text{mm}$  D2 2
--











4



5











6.5x48x16 F2 4	8x30mm A 8	L=450mm L R 1	6.3x13mm M2 8	3.5x13mm P5 2	T15 2
----------------------	------------------	---------------------	---------------------	---------------------	----------




7

6,4 x 50mm		
		
B	O	E1
4	1	4





8



6,4 x 50mm		
		
B	O	E1
4	1	4

9






10

+3.0x20mm







P7

6




11


$\pm 4.0 \times 45 \text{mm}$  P4 2	 E9 2	$\pm 4.0 \times 35 \text{mm}$  R3 4	$\pm 3.5 \times 13 \text{mm}$  P5 2
--	---	--	--



2.






3.




12

$\pm 5/19 \text{mm}$  J 4







1.



2.



3.







M4x22mm		3.0x20mm
		
U	S	P7
2	1	2

8x20x100mm





T14

2






15



	
†35/0mm HG	†3.5x13mm P5
2	4





16





M4x27mm	
	
U8	S
2	1





KUH.70825




KUH.70825





4.0x27mm



x2

4.0x27mm

