
























TURB02







TURB02


A1 8 x 35 mm x12 	E0 $\varnothing 16$ x10 	E1 15 x 12 mm x10 
F1 6 x 34 mm x10 	N5 3,5 x 16 mm x8 	O2 x4 
W x4 	Z x1 	






TURB02





1	1200	700	25	x1	2/2
2	725	690	25	x1	2/2
3	725	690	25	x1	1/2
4	1146	393	16	x1	2/2





1 ►







2 ►





3▶








4▶






5▶



6▶



7 ▶



8 ▶

