






1x1	2x1	3x1	4x1	5x1	6x1
7x1	8x1	9x1	10x1	11x1	12x1
13x3	Ax12	Bx11	Cx10	Dx1	
	 6*35MM	 6*30MM	 6*13MM		




STEP 1




G	x6
	
6*35MM	

STEP2




A	x1	C	x1
			
6*35MM		6*13MM	

STEP 3




A	x3	C	x2
			
6*35MM		6*13MM	

STEP 4



A	x2	C	x1
			
6*35MM		6*13MM	

STEP 5




C x6



6*13MM

STEP 6



B x11



6*30MM