



05697777/03







PART LIST




















2 PEOPLE



HARDWARE LIST




STEP 1




J	X4	K	X1
			
DIA5x50mm		M3	

STEP 2




J	X9	C	X6
			
DIA5x50mm		DIA8x35mm	



STEP 3



STEP 4





STEP 5



A	X2
	
DIA15x11mm	

C	X2	I	X2
			
DIA8x35mm		DIA15mm	



STEP 6



A	X8
	
DIA15x11mm	

C	X6	I	X8
			
DIA8x35mm		DIA15mm	

STEP 7




I	X6
	
DIA15mm	


A	X6
	
DIA15x11mm	

C	X4
	
DIA8x35mm	

STEP 8



STEP 9



B X12



DIA6x40mm

A X8




DIA15x11mm

I X8





DIA15mm

STEP 10





STEP 11




A	X4	I	X4
			
DIA15x11mm		DIA15mm	

STEP 12



A	X4	B	X4	I	X4
					
DIA15x11mm		DIA6x40mm		DIA15mm	

STEP 13



G X4



F X4




M4x25mm

E X8










DIA3x30mm



STEP 14



STEP 15



STEP 17



STEP 18

