




# 81811022



MX Logistika SL, spol.s.r.o.,  
Rožnavská 32,  
82104 Bratislava, Slovakia.  
[www.moebelix.com](http://www.moebelix.com)  
[info@moebelix.at](mailto:info@moebelix.at)  
Származási hely: Kína  
Forgalmazza:  
MMXH Lakberendezési Kft.,  
Soroksári út. 86,  
H-1095 Budapest.

MOTOR:50W  
BULB:1×max 60W E27  
INPUT:220-240V~ 50Hz







**C** x6




**D** x6




**O**




**E** x1



**A**



**H**




x2

**N**




x3

**M**



x1

**F**





x 18

**G**



x2





#8







E 27







1




I x4



2





H x2




J x3






B





3






4




5




6









8




➤  +  x4


9




10





11





(K) x 12



12



13



A warning box with a grey background. In the top right corner, there is a broken glass icon and a warning triangle icon. In the center, a screwdriver is shown with a large 'X' over it, indicating it should not be used. In the bottom left corner, there is a circular icon with the letter 'E'. In the bottom right corner, there is a line drawing of a light fixture.

15

